

WB=CellDBorDBu
total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ feet _____ tons.
N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, madders, and of the inner bottom plating, especially in the boiler space.

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.

POSTPONED SURVEYS.

Case of the Steel Y. "BEGA"
No. 7 in Reg. Bk. 318/131 tons, Built 1914 - 1
d. 100 ft Owners New Docks Stn. Transp. Co.
San Lawler (Hedwood) Co.
3. 15 Port of Registry Hedwood
thine 1. 14

due Screw shaft survey due January '16

GOVERNMENT SERVICE.

The Owners state that this vessel is at present in the service of the Admiralty.

Submitted advca be deferred

RHS.
3.4.16

Committee's Minute TUE - 4 APR. 1916


ion

Deferred

FRI 27 OCT. 1916
TUE - 1 MAY. 1917

TUE. NOV. 13 1917.

W.



© 2020

Lloyd's Register
Foundation

W961-0020

remind of survey 3-15 subject to the manner of
the survey to be carried out in accordance with the rules