

2m, 1, 14.

WRECK BOX
No. 31.

31. M/m Ben 968

22 JUN. 14

Received by Chief Ship Surveyor 20.6.14

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Trawler "Arfon" Rpt. mil. No. 2611

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Condition

This vessel has been examined on a slipway, the bottom cleaned and coated and the rudder pintles renewed.

It is submitted the vessel appears worthy to remain as classed with record of survey 6.14, as recommended.

100A1 "Steam Trawler"
6.14 mil.

M. W. H.

20.6.14.

© 2020

Lloyd's Register
Foundation