

Do  
Do  
Do  
Gr  
L

WRECK BOX  
No.

*Check*

Sent to Chief Surveyors

*2/11/10*

Received from Chief Surveyors

VESSEL'S NAME

*St J H 'Abhona'*

Report

*Geo*

No. *29453*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In case which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*First entry*

When due

*4 100 A.1 (Club) Shade dur.*

*2 gms (u st. Leaks) + shade an (st. Leaks)*

*11 B. bul 2 Ba 86 u 3 + 3 1/2 f 149 6564 FPT 506 APT 456*

*FK. 62H. Cum Leaks av 60 B on shade an 159'*

*M*

*RBA*

*2/11/10*



© 2021

W971-0014

Lloyd's Register  
Foundation

PIL

WEI