

Rpt. 8.

(Received at London Office

SAT - 7 APR. 1917

No.

76281

REPORT of SURVEY for REPAIRS, &c.

LIVERPOOL

Date of writing Report April 1917 When handed in at Local Office 5 APR 1917

Port of

No. in Reg. Book.

Survey held at Liverpool

Date, First Survey 9

Last Survey Mar 30 1917

on the Wood, Iron or Steel S.S. 'ABURI'

Master

TONNAGE:-

Built at Belfast

By whom Harland & Wolff

When 1906

MONTH

GROSS 3730

Owners African S.S. Co.

Port belonging to London

UNDER DK 3214

Owners' Address (Eden, Dempster & Co. Ltd. Mgrs)

NET 2324

(If not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock?

Name of Dock Harland & Wolff Destined Voyage

WB=Cell DBorDBa

feet; uE&B

feet; f

feet; f

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B. All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 75786 Port Liverpool

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years	Machinery and Boiler
For Special Survey.	Assigned	Surveys
Date of last Survey and of Periodical Surveys.	expired.	(including date of N.B., if any).
29/100 A/LIN 11.16		25/100 10.14
WELTER DECK WITH FREE		B. S. 12.16
S.S. LIN 11.15		T. S. 11.15

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if a signed) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why

they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition:-

The vessel examined in Dry dock, bottom & rudder now in good condition, cleaned & recoated.

SUMMARY OF DAMAGE REPAIRS:-

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Dblg. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking ditto

Treenails ditto

Breasthooks & Stemson ditto

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting ditto

(State if examined.)

Copper, or I.M. of Wood Vessels

(State if on Felt.)

When put on, Month

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length

size

Rule length

size

Hawser & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel so far as seen is in good & efficient condition & worthy to remain as classed with fresh record of survey LIN 3.17

Survey Fee (per Section 28)

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

Received by me,

10

10

Committee's Minute

Character Assigned

LIVERPOOL

5 APR 1917

100 A/L

Record 3:17

Shelter deck with freeboard

7R

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W972-0096

H.E.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.				WEIGHT REQUIRED by TABLE 30 or 31.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower ...																
	2nd "																
	3rd "																
	Collective Weight.																
	Stream																
	Kedge.....																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]