

# REPORT ON MACHINERY.

No. 17491

Date of writing Report 2<sup>nd</sup> July 1919 When handed in at Local Office 4<sup>th</sup> July 1919 Port of Greenock  
 No. in Survey held at Port - Glasgow Date, First Survey 19<sup>th</sup> June, 1918; Last Survey 19<sup>th</sup> May, 1919  
 Reg. Book. on the Steel Screw Steamship "Levan Dogra" (Number of Visits 4)

Received at London Office WED. JUL. 9 - 1919

Master R. Findlay Built at Port Glasgow By whom built William Hamilton & Co. Ltd Tons } Gross 5559.24  
 Engines made at Glasgow By whom made David Rowan & Co. Ltd when made } Net 3425.35  
 Boilers made at \_\_\_\_\_ By whom made \_\_\_\_\_ when made

Registered Horse Power \_\_\_\_\_ Owners The Shipping Controller Port belonging to London  
 Nom. Horse Power as per Section 28 \_\_\_\_\_ Is Refrigerating Machinery fitted for cargo purposes \_\_\_\_\_ Is Electric Light fitted \_\_\_\_\_

## ENGINES, &c.—Description of Engines

Dia. of Cylinders		Length of Stroke		Revs. per minute	No. of Cylinders		No. of Cranks	
Dia. of Tunnel shaft as per rule as fitted		Dia. of Crank shaft journals as per rule as fitted			Dia. of Screw shaft as per rule as fitted		Material of screw shaft	

Is the screw shaft fitted with a continuous liner the whole length of the stern tube \_\_\_\_\_ Is the after end of the liner made water tight in the propeller boss \_\_\_\_\_  
 If the liner is in more than one length are the joints burned \_\_\_\_\_ If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive \_\_\_\_\_ If two liners are fitted, is the shaft lapped or protected between the liners \_\_\_\_\_ Length of stern bush \_\_\_\_\_

No. of Feed pumps	Diameter of ditto	Stroke	Can one be overhauled while the other is at work
No. of Bilge pumps	Diameter of ditto	Stroke	Can one be overhauled while the other is at work
No. of Donkey Engines	Sizes of Pumps	No. and size of Suctions connected to both Bilge and Donkey pumps	

In Engine Room \_\_\_\_\_ In Holds, &c. \_\_\_\_\_


No. of Bilge Injections \_\_\_\_\_ sizes \_\_\_\_\_ Connected to condenser, or to circulating pump \_\_\_\_\_ Is a separate Donkey Suction fitted in Engine room & size \_\_\_\_\_  
 Are all the bilge suction pipes fitted with roses \_\_\_\_\_ Are the roses in Engine room always accessible \_\_\_\_\_ Are the stances on Engine room bulkheads always accessible \_\_\_\_\_  
 Are all connections with the sea direct on the skin of the ship \_\_\_\_\_ Are they Valves or Cocks \_\_\_\_\_  
 Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates \_\_\_\_\_ Are the Discharge Pipes above or below the deep water line \_\_\_\_\_  
 Are they each fitted with a Discharge Valve always accessible on the plating of the vessel \_\_\_\_\_ Are the Blow Off Cocks fitted with a spigot and brass covering plate Yes.  
 What pipes are carried through the bunkers \_\_\_\_\_ How are they protected \_\_\_\_\_  
 Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times \_\_\_\_\_  
 Are the Bilge Suction Pipes, Cocks, and Valves arranged so as to prevent any communication between the sea and the bilges \_\_\_\_\_  
 Is the Screw Shaft Tunnel watertight \_\_\_\_\_ Is it fitted with a watertight door \_\_\_\_\_ worked from \_\_\_\_\_

## BOILERS, &c.—(Letter for record \_\_\_\_\_) Manufacturers of Steel

Total Heating Surface of Boilers	Is Forced Draft fitted	No. and Description of Boilers	
Working Pressure	Tested by hydraulic pressure to	Date of test	No. of Certificate

Can each boiler be worked separately \_\_\_\_\_ Area of fire grate in each boiler \_\_\_\_\_ No. and Description of Safety Valves to each boiler \_\_\_\_\_  
 Area of each valve \_\_\_\_\_ Pressure to which they are adjusted \_\_\_\_\_ Are they fitted with easing gear \_\_\_\_\_  
 Smallest distance between boilers or uptakes and bunkers or woodwork \_\_\_\_\_ Mean dia. of boilers \_\_\_\_\_ Length \_\_\_\_\_ Material of shell plates \_\_\_\_\_  
 Thickness \_\_\_\_\_ Range of tensile strength \_\_\_\_\_ Are the shell plates welded or flanged \_\_\_\_\_ Descrip. of riveting: cir. seams \_\_\_\_\_  
 long. seams \_\_\_\_\_ Diameter of rivet holes in long. seams \_\_\_\_\_ Pitch of rivets \_\_\_\_\_ Lap of plates or width of butt straps \_\_\_\_\_  
 Per centages of strength of longitudinal joint \_\_\_\_\_ rivets \_\_\_\_\_ Working pressure of shell by rules \_\_\_\_\_ Size of manhole in shell \_\_\_\_\_  
 Size of compensating ring \_\_\_\_\_ No. and Description of Furnaces in each boiler \_\_\_\_\_ Material \_\_\_\_\_ Outside diameter \_\_\_\_\_  
 Length of plain part \_\_\_\_\_ top \_\_\_\_\_ bottom \_\_\_\_\_ Thickness of plates \_\_\_\_\_ crown \_\_\_\_\_ bottom \_\_\_\_\_ Description of longitudinal joint \_\_\_\_\_ No. of strengthening rings \_\_\_\_\_  
 Working pressure of furnace by the rules \_\_\_\_\_ Combustion chamber plates: Material \_\_\_\_\_ Thickness: Sides \_\_\_\_\_ Back \_\_\_\_\_ Top \_\_\_\_\_ Bottom \_\_\_\_\_  
 Pitch of stays to ditto: Sides \_\_\_\_\_ Back \_\_\_\_\_ Top \_\_\_\_\_ If stays are fitted with nuts or riveted heads \_\_\_\_\_ Working pressure by rules \_\_\_\_\_  
 Material of stays \_\_\_\_\_ Area at smallest part \_\_\_\_\_ Area supported by each stay \_\_\_\_\_ Working pressure by rules \_\_\_\_\_ End plates in steam space: \_\_\_\_\_  
 Material \_\_\_\_\_ Thickness \_\_\_\_\_ Pitch of stays \_\_\_\_\_ How are stays secured \_\_\_\_\_ Working pressure by rules \_\_\_\_\_ Material of stays \_\_\_\_\_  
 Area at smallest part \_\_\_\_\_ Area supported by each stay \_\_\_\_\_ Working pressure by rules \_\_\_\_\_ Material of Front plates at bottom \_\_\_\_\_  
 Thickness \_\_\_\_\_ Material of Lower back plate \_\_\_\_\_ Thickness \_\_\_\_\_ Greatest pitch of stays \_\_\_\_\_ Working pressure of plate by rules \_\_\_\_\_  
 Diameter of tubes \_\_\_\_\_ Pitch of tubes \_\_\_\_\_ Material of tube plates \_\_\_\_\_ Thickness: Front \_\_\_\_\_ Back \_\_\_\_\_ Mean pitch of stays \_\_\_\_\_  
 Pitch across wide water spaces \_\_\_\_\_ Working pressures by rules \_\_\_\_\_ Girders to Chamber tops: Material \_\_\_\_\_ Depth and thickness of girder at centre \_\_\_\_\_ Length as per rule \_\_\_\_\_ Distance apart \_\_\_\_\_ Number and pitch of stays in each \_\_\_\_\_  
 Working pressure by rules \_\_\_\_\_ Steam dome: description of joint to shell \_\_\_\_\_ % of strength of joint \_\_\_\_\_

DIAPHRAGM. Type \_\_\_\_\_ Date of Approval of Plan \_\_\_\_\_ Tested by Hydraulic Pressure to \_\_\_\_\_  
 Date of Test \_\_\_\_\_ Is a Safety Valve fitted to each Section of the Superheater which can be shut off from the Boiler \_\_\_\_\_  
 Diameter of Safety Valve \_\_\_\_\_ Pressure to which each is adjusted \_\_\_\_\_ Is Easing Gear fitted \_\_\_\_\_



W489-0037

IS A DONKEY BOILER FITTED?

If so, is a report now forwarded?

SPARE GEAR. State the articles supplied:—

The foregoing is a correct description,

Manufacturer.

Dates of Survey while building (During progress of work in shops - - -) (1918). June 19. (1919). May 6. 15. 19. -  
(During erection on board vessel - - -)  
Total No. of visits 4.

Is the approved plan of main boiler forwarded herewith

" " " donkey " " "

Dates of Examination of principal parts—Cylinders Slides Covers Pistons Rods

Connecting rods Crank shaft Thrust shaft Tunnel shafts Screw shaft Propeller

Stern tube Steam pipes tested Engine and boiler seatings 15/5/19 Engines holding down bolts

Completion of pumping arrangements Boilers fixed Engines tried under steam

Completion of fitting sea connections 19/5/19 Stern tube 19/5/19 Screw shaft and propeller 19/5/19

Main boiler safety valves adjusted Thickness of adjusting washers

Material of Crank shaft Identification Mark on Do. Material of Thrust shaft Identification Mark on Do.

Material of Tunnel shafts Identification Marks on Do. Material of Screw shafts Identification Marks on Do.

Material of Steam Pipes Test pressure

Is an installation fitted for burning oil fuel Is the flash point of the oil to be used over 150°F.

Have the requirements of Section 49 of the Rules been complied with

Is this machinery duplicate of a previous case If so, state name of vessel

General Remarks (State quality of workmanship, opinions as to class, &c.)

Vessel taken to Glasgow for Machinery & Boilers to be fitted.

Certificate (if required) to be sent to

The amount of Entry Fee ... £ : : When applied for, : :  
Special ... £ : : : : 19.  
Donkey Boiler Fee ... £ : : : :  
Travelling Expenses (if any) £ : : : : When received, : :  
: : : : : 19.

Graham Robertson  
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute GLASGOW - 8 JUL 1919

FRI. MAR 19 1920

Assigned See attached machinery report



© 2020

Lloyd's Register Foundation