

Vessel placed on dry dock 11/11/11

3m. 4.21

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel S.S. "HERBERT L. PRATT". Report N. Yk. No. 20356.  
20356-1

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*Damage*

When due \_\_\_\_\_

*Noted.*  
*20.6.11*  
*M*

RETAILED



© 2020

Lloyd's Register Foundation

this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

*This vessel is in good condition, eligible in my opinion to remain*

held on the  
sent, or when  
Committee's M's

Vessels  
Good  
"  
ed from  
moved)  
✓  
5.  
anged)  
✓  
si  
✓  
si  
Good  
Rigging