



# Port Valparaiso

No. 3-10, 37  
No. 1-42  
Examined 2-47  
(months)

Inspected by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "MATIAS COUSINO" REPORT Vpo. No. 2314

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel holds the notation of "Examined 2.47" valid for six months.


The class is subject to the Special Survey being carried out by 8.47 and to the sternframe (E.W. and reinforced 7.44) being specially examined at the next dry docking.

ACTION is DEFERRED (9.47) for a short time pending receipt of information from the VALPARAISO Surveyor as to the disposal of the vessel.

The VALPARAISO Surveyor reports 8.47 the vessel afloat, the General Examination carried out and minor repairs effected.

Owing to the extensive repairs required to deck, tank top plating, bulkheads, shell plates, tunnel etc., the vessel has now been laid up with a view to selling for scrap.

On September 19th, the Committee gave instructions for the notation of "Dismantled" to be inserted in the Register Book.



© 2020  
28.10.47

Lloyd's Register  
Foundation

Chas R. Rouchiffe

Surveyor to Lloyd's Register.

assigned) as  
now verified

nt of s

iliges, t

examined

page)

is :—

, or Y.M.  
ate if on Felt.)  
fitted, Month

Yards, &c.

ion, how ascert  
ate if wedges res  
ment letter

rs, No. of

(State if now ra

length

length on board

Rule length

Locker

Mast & Warps

Standing and Running

Sails