

May 24

I here by Certify that in Oct^r 1832
the Schooner Mary of Weyford (etc)
Deceased Master was repaired with M^r
John Benson Master Shipwright in the port
of Milford Under my inspection (as per mem
to him) With 30 or 40 New first and second
guths All new Cubing One New Breast
Hook One New lower transom New Bilge
Planks Several Shifts of Plank from the
Bidge to the Main Wales all New trenails
And fastened Several New planks in both
Hats of the Bottom on the Out Side New
Windlass Bits & Pins with Other Repairs
Which amounted to £290-0-0

And in June 1834 the aforesaid Schooner was
repaired by the M^r with two New clock Beams
Seven New Pins New coumings to the
Main hatch Way New Oak Deck from
the fore part of Main hatch way to the fore
Mast & Midships a great part of New Decks
from the Waterways to the hatch Ways New
Stearns New transom Beam & Pins
Caulk^d all close with Several Other Repairs
Which amounted to £100-0-0
Milford January 16 1835

John Benson Master Shipwright



© 2021

Lloyd's Register
Foundation

WEX1031-0028