

2nd. On the plating during the process of riveting Jan 8. 9. 14. 24. Feb 6. 19. 21. 22. 23. 24 March  
3rd. When the beams were in and fastened. 18. 19. 21. 22. 23. 24 March

*[Signature]*  
REPORT, No. 3672 FROM Barrow  
ON THE Pembroke Castle

DATE

13/8/83

REMARKS OF THE CHIEF SURVEYOR.

It is submitted that this vessel appears eligible for the favourable consideration of the committee to be classed 100 A. 1. Steel

H.H

3 decks (2 steel)

3 tiers of beams.

D.B see particulars



WHN1036-0208

Bridge Deck 169.0' Holes on Bridge 52.0 + 12.2' Deck Holes off side