

1 Waterford 51
We the Undersigned at the request of
Capt. Thomas Hayes of the Brig Mercury
of Waterford now lying on the Bank
Did then and there survey Examine and
carefully Inspect inside and out, in taking
up some Ceiling plank in the Bilges and
other parts, also some Copper off the Bottom
and Bilges & wooden ends

We find the Timbers and plank perfectly
sound, and recommend the Ceiling to be replaced,
some Copper Nails & Bolts put in the Plank
outside above the Bilge, one New Breast hook,
the other fastened, to put one long Iron Strap
outside below the Port, to Cauch the Seams
& Hoardings, & replace the Copper to enable her
to proceed on any Voyage she may be sent.

Given Under Our Hands
in Waterford 27 Jan'y 1836
Michael Power
James Morris } Ship Master

William Smith Shipbuilder
and Surveyor of Shipping
Lloyd's Register
Foundation